



Environmental Monitoring and Technical Services
2392 Kincaid Road MS 45A. San Diego, CA 92101
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services
Lead School Testing
Report Date: 4/18/17


San Diego Unified School District
Valencia Park Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1165257	04/08/17	07:48 AM	SAMPLE 1	3710020-ACJ-A	< 5	ug/L
W1165258	04/08/17	07:54 AM	SAMPLE 2	3710020-ACJ-B	< 5	ug/L
W1165259	04/08/17	08:00 AM	SAMPLE 3	3710020-ACJ-C	< 5	ug/L
W1165260	04/08/17	08:03 AM	SAMPLE 4	3710020-ACJ-D	< 5	ug/L
W1165261	04/08/17	08:07 AM	SAMPLE 5	3710020-ACJ-E	< 5	ug/L

Source **Source Description**

- SAMPLE 1 Boys and Girls Bathroom next to Supply Room 21008, triple fountain left bubbler
- SAMPLE 2 Auditorium Cafeteria Prep kitchen sink faucet
- SAMPLE 3 Between Library and Room 19, dual fountain right bubbler
- SAMPLE 4 Between Room 17 and 18, triple fountain, middle bubbler
- SAMPLE 5 Boys and Girls Bathroom outside playground, dual fountain, right bubbler

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L
Action Level (AL) = 15 ug/L


Tom Burger, Associate Chemist