



Water Quality Chemistry Services Lead School Testing Report Date: 5/23/17

San Diego Unified School District Wegeforth Elementary

Sample ID	Sample Date	Sample Time	Source	External ID	Lead	Units
W1168196	04/22/17	09:07 AM	SAMPLE 1	3710020-AJH-A	5.85	ug/L
W1168197	04/22/17	09:11 AM	SAMPLE 2	3710020-AJH-B	6.12	ug/L
W1168198	04/22/17	09:14 AM	SAMPLE 3	3710020-AJH-C	< 5	ug/L
W1168199	04/22/17	09:18 AM	SAMPLE 4	3710020-AJH-D	5.16	ug/L
W1168502	04/25/17	07:02 AM	SAMPLE 5	3710020-AJH-E	6.83	ug/L

Source	Source Description		
SAMPLE 1	Assembly- Cafeteria; West wall of Kitchen; Faucet on a 2-compartment sink		
SAMPLE 2	Kindergarten Bldg.; Exterior east wall; Sample from R-side Bubbler on a drinking fountain with a faucet		
SAMPLE 3	Classroom Bldg. East; : Exterior North wall; Right bubbler on a triple drinking fountain		
SAMPLE 4	Classroom Bldg. West; Exterior south wall ; Right bubbler on a double drinking fountain		
SAMPLE 5	Admin./Cafeteria Bldg. at CDC; Interior South wall of cafeteria; Right Bubbler on the R-side sink		

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L Action Level (AL) = 15 ug/L $\,$

Doug Campbell, Senior Chemist