



Environmental Monitoring and Technical Services  
2392 Kincaid Road MS 45A, San Diego, CA 92101  
Tel(619) 758-2300 Fax (619) 758-2309

Water Quality Chemistry Services  
Lead School Testing  
Report Date: 6/7/17

San Diego Unified School District  
**Whittier K-12**

| Sample ID | Sample Date | Sample Time | Source   | External ID   | Lead | Units |
|-----------|-------------|-------------|----------|---------------|------|-------|
| W1173120  | 05/24/17    | 06:18 AM    | SAMPLE 1 | 3710020-CAF-A | < 5  | ug/L  |
| W1173121  | 05/24/17    | 06:08 AM    | SAMPLE 2 | 3710020-CAF-B | 5.19 | ug/L  |
| W1173122  | 05/24/17    | 06:06 AM    | SAMPLE 3 | 3710020-CAF-C | < 5  | ug/L  |
| W1173123  | 05/24/17    | 06:10 AM    | SAMPLE 4 | 3710020-CAF-D | < 5  | ug/L  |
| W1173124  | 05/24/17    | 06:13 AM    | SAMPLE 5 | 3710020-CAF-E | < 5  | ug/L  |

**Source**      **Source Description**

- SAMPLE 1      Building A, Kitchen, Sink along south wall, faucet above two compartment sink
- SAMPLE 2      Building A, West facing wall outside of Auditorium door, three single bubbler fountains, upper right fountain
- SAMPLE 3      Building D, East facing wall next to girls RR, two single bubbler fountains, upper left fountain
- SAMPLE 4      Building F, Northeast corner of building, two single bubbler fountains, upper left fountain
- SAMPLE 5      Building B, Northwest corner of building next to girls RR, two single bubbler fountains, upper right fountain

DLR= State Mandated Detection Limit for Reporting (DLR)= 5 ug/L  
Action Level (AL) = 15 ug/L

  
Doug Campbell, Senior Chemist